



Affordable RV Parts



REPAIR PARTS LIST FOR 470X4A87X MACH 8 SERIES 15,000 BTU HEAT PUMP (Serial Numbers 1501 and higher)

(Includes 47054A876,47054A879, 47074A876, 47074A879, 47004A876, 47004A879, 47024A876, 47024A879)

NOTE: ORDER PARTS LISTED ARE THE ONLY PARTS AVAILABLE FOR ORDERING

CODE	USED ON MODELS	ORDER PART	DESCRIPTION	NO. REQ.
1.	876	47233-3261	Shroud (Arctic White/Arctic White)	1
	879	47233-3291	Shroud (Black/Black)	1
14.	All	1468A3389	Indoor Motor	1
16.	All	1472A1191	Blower Wheel	1
19.	All	1499-5721	Run Capacitor (40 Mfd/370v)	1
20.	All	9333-9021	Start Device Pkg. (88-108 Mfd/250V)	1
24.	All	1472D5041	Fan Blade	1
27.	All	1468A3399	Outdoor Motor	1

ns = not shown

SPECIAL ORDER PARTS:

NOTE: All parts with three-digit suffix numbers are “Special Order” Parts. These parts are subject to factory availability and require extra time for delivery.

NOTE: Heat Strip Assemblies CANNOT be used with the Top-Down Models.

NOTE: For Ordering Assistance Please Visit Our [HOMEPAGE](#)

SCHEMATIC FOR PARTS – SEE NEXT PAGE

