



Affordable RV Parts



[HOMEPAGE](#)

**REPAIR PARTS LIST
FOR
6537*871 (-, A, B) SERIES
HIGH EFFICIENCY
2-TON PACKAGED HEAT PUMP (TALL)
(Includes 6537-871, 6537A871, 6537B871)**

NOTE: ORDER PARTS LISTED ARE THE ONLY PARTS AVAILABLE FOR ORDERING

CODE	USED ON MODELS	ORDER PART	DESCRIPTION	NO. REQ.
16.	871	1450-2149	Compressor	2
18.	All	6759-3081	Compressor Foot Pkg. (3/Pkg.)	2
23.	All	1472-1161	O.D. Blower Wheel	1
28.	All	1468A3029	O.D. Blower Motor	1
29.	All	1499-5631	O.D. Blower Capacitor (12.5 Mfd/370V)	1
32.	All	6536-3011	Pillow Block Bearing (I.D. or O.D.)	1
36.	All	1468A3219	I.D. Blower Motor (Reversible)	1
39.	All	1460-1131	Compressor Relay	2
40.	871	1499-5671	Compressor Run Capacitor (30 Mfd/370V)	2
43.	All	8333A9021	Start Device	2
44.	All	6536C3209	P.C. Board Kit	1
45.	All	1499-5461	I.D. Blower Capacitor (7.5 Mfd/370V)	1

ns = not shown

NOTE: All parts with three digit suffix numbers are "Special Order" Parts. These parts are subject to factory availability and require extra time for delivery.

NOTE: For Ordering Assistance Please Visit Our [HOMEPAGE](#)

SCHEMATIC FOR PARTS – SEE NEXT PAGE

